

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**







Figure 2



Coating
Surface

Type I (Pore Size)A > (Pore Size)B

Type II (Pore Size)A = (Pore Size)B

Type IV (Pore Size)A = (Pore Size)C > (Pore Size)B

Type V (Pore Size)A = (Pore Size)C < (Pore Size)B

Type VI (Pore Size)A > (Pore Size)B > (Pore Size)C

Type VII (Pore Size)C > (Pore Size)B > (Pore Size)A

Figure 3



3/14




Figure 4. 0228sd67.5



4/14




Figure 5. Cross-section of 0410S67.5



5/14





Figure 6. Close-up of 0410S67.5



Figure 7





Forward Flow Bubble Point
in 60/40 IPA/H₂O PVDF Membrane - 90 mm Disc




Figure 8




Figure 9



9/14




Figure 10. Cross section of 0508lam



10/14



Figure11. Close up of Figure 10



Forward Flow Bubble Point in 60/40 IPA/H₂O
Bobcat Casting Trial - Sample 206




Figure 12



12/14




Figure 13. Cross-section of membrane # 0103



Forward Flow Bubble Point in 60/40 IPA/H₂O Nylon Membrane Sample 103




Figure 14



14/14




Figure 15. Order of dope application: slot C, B, A